

BONE Fatigue

The B-1 was designed to be a penetrating bomber, flying fast and low with swept wings. In Afghanistan, however, close air support duties meant loitering at high altitudes, heavily loaded, with wings swept forward, before dashing at high-speed to respond when needed. The unanticipated stress caused cracks in highly stressed structural components joining the wings to the fuselage.

